





C A M B R I A

EXPLANATION

 Groundwater monitoring well

 Destroyed groundwater monitoring well

Cutten Inn Restaurant

MW -2

Approximate
Location of
Former Waste
Oil Tank

Residences

Nilsen Real
Estate
Appraisals

Farmer's Insurance Group

MW -5

Fenced Area

MW -4

Former UST
Complex


MW -1

MW -3

WALNUT DRIVE

Humboldt Petroleum, Inc.
Shell Service Station

FERN STREET



Scale (ft)



FIGURE

2